

Please access the AT-D578UV Menu-Setting-Device Info to check the version first before upgrade.  
 Make sure the radio is upgraded to the latest version to get the BT-01 microphone working correctly.  
 Reset must be done to the radio after the firmware upgrade.

	Model Name	Firmware	SCT3258	BT module Software	APRS+BT board	CPS Version	BT01 Version
AT-D578UV/ AT-D578UVIII No GPS, No BT	D578UV	Ver1.17	V2.01.07BF	X	X	V1.17	V1.00h
AT-D578UV PRO/ AT-D578UVIII PRO With GPS and BT	D578UV	Ver1.17	V2.01.07BF	ET12_AQQX_ V10043	X	V1.17	V1.00h
AT-D578UV PLUS/ AT-D578UVIII PLUS With GPS,BT and APRS	D578UVII	Ver2.04	V2.01.07BF	ET12_AQQX_ V10043	V1.06	V1.17	V1.00h