

www.Anytone.US

D878UV firmware update V1.23 (dated 2021-04-13)

Change List

1. Resolve the issue that the talker alias transmit doesn't match to selected Radio ID
2. CPS->Tool -> Options, add Analog APRS RX option, allows user choose whether the Analog aprs RX setting is valid according to the radio version.
3. Resolve the issue that "when sending APRS Beacon it transmits three times instead of once, when transmitting APRS Beacon with PTT it transmits it twice instead of once"

Firmware version: V1.23

CPS version: V1.23

SCT 3258 version: V2.01.07 BA (same, no need update)

BT Version: 10033